

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2017 Levee Inspection Results

Levee District No. 0001 (Glenn County)

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

† SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2017 Levee Inspection Results

Levee District No. 0001 (Glenn County)

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	12.23
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/28/2017 - 3/28/2017			
DWR Inspector	Bob Duffey			
Accompanied By	Bill Carriere LD1G			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals				
DWR ID	DWR_LD0001G_01_s_2013_5				
Comment Code					
Inspector Comment					
The LMA has copies of the O&M manuals.					

No Photos

LM Start		Rating **	M	Issue No.	9
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment				
DWR ID	DWR_LD0001G_01_s_2013_9				
Comment Code					
Inspector Comment					
The LMA does not have adequate emergency supplies and equipment.					

No Photos

LM Start		Rating **	M	Issue No.	14
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training				
DWR ID	DWR_LD0001G_01_s_2013_14				
Comment Code					
Inspector Comment					
Its been a while since the LMA has completed the flood fight training in the past.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	0.02	Rating **	M	Issue No.	73
LM End	0.04	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.477372 °	39.477833 °
				-122.017602 °	-122.017484 °
DWR ID	DWR_LD0001G_01_s_2016_73				
Comment Code					
EQ : Equipment					
Inspector Comment					
Remove ag equipment at LS toe.					

Photo 1 of 1 : SP_2017_LD0001G_432_73_20170315_00037.jpg



View of the prunings pile and ag equipment at the landside toe.

LM Start	0.05	Rating **	M	Issue No.	40
LM End	0.05	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.477833 °	39.477833 °
				-122.017484 °	-122.017484 °
DWR ID	DWR_LD0001G_01_s_2016_40				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings at LS toe.					

Photo 1 of 1 : SP_2017_LD0001G_432_40_20170330_00121.jpg



View of the prunings along the landside slope and toe.

LM Start	0.25	Rating **	M	Issue No.	41
LM End	0.25	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.480769 °	39.480769 °
				-122.017301 °	-122.017301 °
DWR ID	DWR_LD0001G_01_f_2015_41				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove tree from the waterside slope.					

Photo 1 of 2 : SP_2017_LD0001G_432_41_20170315_00010.jpg



View of the tree on the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	0.25	Rating **	M	Issue No.	41 (cont)	
LM End	0.25	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			39.480769 °		39.480769 °
				-122.017301 °		-122.017301 °
DWR ID	DWR_LD0001G_01_f_2015_41					
Comment Code						
TR : Tree or limb						
Inspector Comment						
Remove tree from the waterside slope.						

Photo 2 of 2 : SP_2017_LD0001G_432_41_20170315_00011.jpg



View of the fallen tree on the waterside slope looking upstream.

LM Start	0.77	Rating **	M	Issue No.	396
LM End	0.77	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.487806 °	39.487806 °
				-122.019414 °	-122.019414 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14324 DS_ID:22893 EP_NO: 11782 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 5/29/2013 - Siphon breaker missing from WS shoulder (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 3-inch galvanized steel pipe through levee, 2 feet below the crown. There is a hose bib style siphon breaker on the waterside (WS) shoulder. A pipe runs from the concrete sump next to the barn on the landside (LS) to a cesspool off of the WS toe (Permit No. 11782, 1977 - Carriere Brothers). [Additional Reference(s): DWR Levee Logs, 1992] FS Date: 5/29/2013					

Photo 1 of 3 : UCIP_SP_2017_14324_23564.jpg



3-inch pipe at cesspool off WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	0.77	Rating **	M	Issue No.	396 (cont)
LM End	0.77	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.487806 °	39.487806 °
				-122.019414 °	-122.019414 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14324 DS_ID:22893 EP_NO: 11782 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 5/29/2013 - Siphon breaker missing from WS shoulder (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 3-inch galvanized steel pipe through levee, 2 feet below the crown. There is a hose bib style siphon breaker on the waterside (WS) shoulder. A pipe runs from the concrete sump next to the barn on the landside (LS) to a cesspool off of the WS toe (Permit No. 11782, 1977 - Carriere Brothers). [Additional Reference(s): DWR Levee Logs, 1992] FS Date: 5/29/2013					

LM Start	0.77	Rating **	M	Issue No.	396 (cont)
LM End	0.77	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_14324_23563.jpg



Concrete sump next to barn off LS toe.

Photo 3 of 3 : UCIP_SP_2017_14324_23562.jpg



Concrete sump next to barn off LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	0.80	Rating **	M	Issue No.	397
LM End	0.80	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.488160 °	39.488160 °
				-122.019888 °	-122.019888 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14325					
DS_ID:22894					
EP_NO: 1837					
Repair Type: Non-Urgent					
Crossing Status: Indicator Found					
UCIP Comments: 5/29/2013 - Gasline appears abandoned, need to verify abandonment or mark actual pipe location. (W. Wylie - DWR UCIP)					
FIELD_STRUCT_DESC: 3-inch gas line of an unknown material through the levee, 2 feet below the crown (Permit No. 1837, 1959 - Sunray Oil Corporation). Fenced in pumping plant area next to levee with appurtenances. [Additional Reference(s): DWR Levee Logs, 1992].					
FS Date: 5/29/2013					

Photo 1 of 3 : UCIP_SP_2017_14325_23568.jpg



Gas pumping plant and appurtenances.

LM Start	0.80	Rating **	M	Issue No.	397 (cont)
LM End	0.80	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_14325_23567.jpg



Possible pipe at crossing, LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	0.80	Rating **	M	Issue No.	397 (cont)	
LM End	0.80	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.488160 °		39.488160 °
				-122.019888 °		-122.019888 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14325 DS_ID:22894 EP_NO: 1837 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: 5/29/2013 - Gasline appears abandoned, need to verify abandonment or mark actual pipe location. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 3-inch gas line of an unknown material through the levee, 2 feet below the crown (Permit No. 1837, 1959 - Sunray Oil Corporation). Fenced in pumping plant area next to levee with appurtenances. [Additional Reference(s): DWR Levee Logs, 1992]. FS Date: 5/29/2013						

Photo 3 of 3 : UCIP_SP_2017_14325_23566.jpg



Gas pumping plant and appurtenances.

LM Start	1.01	Rating **	M	Issue No.	43
LM End	1.01	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.490963 °	39.490963 °
				-122.020510 °	-122.020510 °
DWR ID	DWR_LD0001G_01_f_2016_43				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_43_20170315_00012.jpg



View of the tree limbs on the landside slope.

* Location
 LS : Land Side N/A : Not Applicable
 WS : Water Side
 CR : Crown

** Rating
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 N : Not Inspected/Rated
 C : Corrected
 A/W : Acceptable but Monitor & Maintain

+ Issue Type
 Ma : Maintenance Deficiency
 Ob : Design & System Obsolescence
 En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	1.09	Rating **	M	Issue No.	398
LM End	1.09	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.492090 °	39.492090 °
				-122.020014 °	-122.020014 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14326 DS_ID:22895 EP_NO: 2171 Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: Need to determine disposition of this pipe. FIELD_STRUCT_DESC: 1 of 2: 3-inch gas pipe of unknown material through the levee, 2 feet below the crown (Permit No. 2171, 1958 - Sunray Mid-Continent Oil Company). [Additional Reference(s): DWR Levee Logs, 1992]. FS Date: 5/29/2013					

No Photos

LM Start	1.09	Rating **	M	Issue No.	74
LM End	1.17	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.492090 °	39.492090 °
				-122.020014 °	-122.020014 °
DWR ID	DWR_LD0001G_01_s_2016_74				
Comment Code					
AV : Abandoned vehicles					
Inspector Comment					
Abandoned vehicles and equipment at LS toe.					

Photo 1 of 1 : SP_2017_LD0001G_432_74_20170315_00038.jpg



View of vehicles & equipment along the L/S toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	1.11	Rating **	M	Issue No.	4
LM End	1.11	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.491887 °	39.494572 °
				-122.020238 °	-122.017840 °
DWR ID	DWR_LD0001G_01_s_2012_4				
Comment Code					
BU : Building					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_4_20170315_00001.jpg



View of unpermitted building L/S toe.

LM Start	1.15	Rating **	M	Issue No.	58
LM End	1.15	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.492788 °	39.492788 °
				-122.019437 °	-122.019437 °
DWR ID	DWR_LD0001G_01_s_2015_58				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings at LS toe.					

Photo 1 of 1 : SP_2017_LD0001G_432_58_20170315_00024.jpg



View of the prunings along the waterside toe.

LM Start	1.22	Rating **	M	Issue No.	59
LM End	1.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.493667 °	39.493667 °
				-122.018643 °	-122.018643 °
DWR ID	DWR_LD0001G_01_f_2015_59				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
The levee district has a rodent program in place.					

Photo 1 of 2 : SP_2017_LD0001G_432_59_20170315_00025.jpg



View of the rodent holes along the landside slope.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	1.22	Rating **	M	Issue No.	59 (cont)	
LM End	1.22	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Animal Control			39.493667 °		39.493667 °
				-122.018643 °		-122.018643 °
DWR ID	DWR_LD0001G_01_f_2015_59					
Comment Code						
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.						
Inspector Comment						
The levee district has a rodent program in place.						

Photo 2 of 2 : SP_2017_LD0001G_432_59_20170315_00026.jpg



View of the rodent holes along the landside slope.

LM Start	1.25	Rating **	M	Issue No.	399
LM End	1.25	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.493977 °	39.493977 °
				-122.018380 °	-122.018380 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14327					
DS_ID:22896					
EP_NO: 2171					
Repair Type: Non-Urgent					
Crossing Status: Indicator Found					
UCIP Comments: Appears abandoned as well off LS toe has been removed. Need to remove from levee or mark as appropriate.					
FIELD_STRUCT_DESC: 2 of 2: 3-inch gas pipe of unknown material through the levee, 2 feet below the crown. Abandoned gas-pump station 260-feet off LS toe. (Permit No. 2171, 1958 - Sunray Mid-Continent Oil Company). [Additional Reference(s): DWR Levee Log, 1992]					
FS Date: 5/29/2013					

Photo 1 of 1 : UCIP_SP_2017_14327_23569.jpg



Gasline markers near where removed pumping plant was located.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	1.32	Rating **	A/W	Issue No.	6
LM End	1.36	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.494828 °	39.495330 °
				-122.017632 °	-122.017163 °
DWR ID	DWR_LD0001G_01_s_2012_6				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Landscaping Permit No. 13057					

Photo 1 of 1 : SP_2017_LD0001G_432_6_20170315_00002.jpg



View of the permitted landscape on the landside slope of the levee.

LM Start	1.97	Rating **	M	Issue No.	400
LM End	1.97	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.499823 °	39.499823 °
				-122.009971 °	-122.009971 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14328					
DS_ID:22897					
EP_NO: 14759					
Repair Type: Non-Urgent					
Crossing Status: Not Found					
UCIP Comments: Appears to have been abandoned. Should be removed or marked as necessary.					
FIELD_STRUCT_DESC: 4-inch natural gas line of unknown material through levee, 0.17 feet below crown. (Permit No. 14759, 1987 - TXO Production Corp). [Additional Reference(s): DWR Levee Log, 1992]					
FS Date: 5/29/2013					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	2.22	Rating **	M	Issue No.	401
LM End	2.22	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.501690 °	39.501690 °
				-122.006100 °	-122.006100 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14331					
DS_ID:22898					
EP_NO: 5717A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Pipe abandoned and should be done so properly.					
FIELD_STRUCT_DESC: 8-inch asbestos cement irrigation pipe sleeved through 12-inch though the levee, 5 feet below the crown. Pump is located on the landside (LS). Meter pole located on the LS toe, guy wire anchor in LS slope. (Permit No. 5717A, 1969 - W. A. Carriere).					
[Additional Reference(s): DWR Levee Log, 1992]					
FS Date: 5/29/2013					

Photo 1 of 2 : UCIP_SP_2017_14331_23579.jpg



Pump at LS toe with no connection to 8-inch pipe.

LM Start	2.22	Rating **	M	Issue No.	401 (cont)
LM End	2.22	Issue Type +	En	Location *	LS

Photo 2 of 2 : UCIP_SP_2017_14331_23578.jpg



8-inch pipe visible at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	2.22	Rating **	M	Issue No.	402
LM End	2.22	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.501690 °	39.501690 °
				-122.006099 °	-122.006099 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:14332
DS_ID:22944
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Appears abandoned and should be done so properly.
FIELD_STRUCT_DESC: *ABANDONED* 8-inch pipe of unknown material sleeved through a 12-inch pipe of unknown material through levee, 9.5 feet below crown. Flap gate is located on the waterside (WS). Pipe is opened on the landside (LS). [Additional Reference(s): USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 2.27)].
FS Date: 5/29/2013

LM Start	2.22	Rating **	M	Issue No.	402 (cont)
LM End	2.22	Issue Type +	Ma	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_14332_23582.jpg



Pump at location of pipe on LS toe.

Photo 2 of 3 : UCIP_SP_2017_14332_23581.jpg



Pipe next to pump at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	2.22	Rating **	M	Issue No.	402 (cont)	
LM End	2.22	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.501690 °	39.501690 °	
				-122.006099 °	-122.006099 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14332						
DS_ID:22944						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Appears abandoned and should be done so properly.						
FIELD_STRUCT_DESC: *ABANDONED* 8-inch pipe of unknown						
material sleeved through a 12-inch pipe of unknown material through						
levee, 9.5 feet below crown. Flap gate is located on the waterside						
(WS). Pipe is opened on the landside (LS). [Additional Reference(s):						
USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 2.27)].						
FS Date: 5/29/2013						

Photo 3 of 3 : UCIP_SP_2017_14332_23580.jpg



8-inch pipe sleeved through a 12-inch concrete pipe.

LM Start	2.48	Rating **	M	Issue No.	61
LM End	2.48	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.505237 °	39.505237 °
				-122.006493 °	-122.006493 °
DWR ID	DWR_LD0001G_01_s_2015_61				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from the LS toe.					

Photo 1 of 2 : SP_2017_LD0001G_432_61_20170315_00027.jpg



View of the prunings along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	2.48	Rating **	M	Issue No.	61 (cont)	
LM End	2.48	Issue Type +	En	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			39.505237 °		39.505237 °
				-122.006493 °		-122.006493 °
DWR ID	DWR_LD0001G_01_s_2015_61					
Comment Code						
PR : Prunings						
Inspector Comment						
Remove prunings from the LS toe.						

Photo 2 of 2 : SP_2017_LD0001G_432_61_20170315_00028.jpg



View of the prunings along the landside toe.

LM Start	2.80	Rating **	M	Issue No.	49
LM End	2.80	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.509503 °	39.509503 °
				-122.008732 °	-122.008732 °
DWR ID	DWR_LD0001G_01_f_2014_49				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_49_20170315_00016.jpg



View of the prunings along the landsides toe.

LM Start	2.80	Rating **	M	Issue No.	50
LM End	2.80	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.509503 °	39.509503 °
				-122.008732 °	-122.008732 °
DWR ID	DWR_LD0001G_01_f_2014_50				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_50_20170315_00017.jpg



View of the rodent activity along the landside slope.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	2.87	Rating **	M	Issue No.	62
LM End	2.87	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.510492 °	39.510492 °
				-122.009023 °	-122.009023 °
DWR ID	DWR_LD0001G_01_s_2015_62				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove pruning from the WS toe.					

Photo 1 of 1 : SP_2017_LD0001G_432_62_20170315_00029.jpg



View of the pruning on the waterside toe.

LM Start	3.04	Rating **	U	Issue No.	51
LM End	3.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.512818 °	39.513870 °
				-122.009027 °	-122.010078 °
DWR ID	DWR_LD0001G_01_f_2014_51				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the levee slope damaged by rodent activity.					

Photo 1 of 2 : SP_2017_LD0001G_432_51_20170315_00019.jpg



View of the rodent holes along the landside slope.

LM Start	3.04	Rating **	U	Issue No.	51 (cont)
LM End	3.13	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP_2017_LD0001G_432_51_20170330_00120.jpg



View of the rodent holes along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	3.04	Rating **	M	Issue No.	45
LM End	3.04	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.512914 °	39.512914 °
				-122.009063 °	-122.009063 °
DWR ID	DWR_LD0001G_01_s_2014_45				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings pile at the landside toe.					

No Photos

LM Start	3.13	Rating **	M	Issue No.	403
LM End	3.13	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.513835 °	39.513835 °
				-122.010029 °	-122.010029 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:16223 DS_ID:22901 EP_NO: 9575 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Appears to have been abandoned. Need to verify pipe was grouted/abandoned properly. FIELD_STRUCT_DESC: *ABANDONED* 12-inch pipe through levee 14.0 feet below crown. Flap Gate on waterward end (ABO No. 9575, 1974). [Additional Reference(s): DWR Levee Log, 1992]. FS Date: 5/29/2013					

Photo 1 of 2 : UCIP_SP_2017_16223_27343.jpg



Flap gate visible at WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	3.13	Rating **	M	Issue No.	403 (cont)	
LM End	3.13	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.513835 °	39.513835 °	
				-122.010029 °	-122.010029 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:16223						
DS_ID:22901						
EP_NO: 9575						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Appears to have been abandoned. Need to verify pipe was grouted/abandoned properly.						
FIELD_STRUCT_DESC: *ABANDONED* 12-inch pipe through levee 14.0 feet below crown. Flap Gate on waterward end (ABO No. 9575, 1974). [Additional Reference(s): DWR Levee Log, 1992].						
FS Date: 5/29/2013						

Photo 2 of 2 : UCIP_SP_2017_16223_27342.jpg



Flap gate visible at WS toe.

LM Start	3.19	Rating **	M	Issue No.	16
LM End	3.19	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.514709 °	39.514709 °
				-122.010515 °	-122.010515 °
DWR ID	DWR_LD0001G_01_s_2012_16				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_16_20170315_00007.jpg



View of the pruning pile along the L/S toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	3.39	Rating **	M	Issue No.	46
LM End	3.39	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.517389 °	39.517389 °
				-122.010685 °	-122.010685 °
DWR ID	DWR_LD0001G_01_s_2016_46				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_46_20170315_00013.jpg



View of the prunings along the landside slope.

LM Start	3.63	Rating **	M	Issue No.	56
LM End	3.63	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.520623 °	39.520623 °
				-122.010457 °	-122.010457 °
DWR ID	DWR_LD0001G_01_f_2013_56				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_56_20170315_00022.jpg



View of the prunings and limbs along the slope of the levee.

LM Start	3.86	Rating **	M	Issue No.	23
LM End	3.86	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.523660 °	39.523660 °
				-122.010863 °	-122.010863 °
DWR ID	DWR_LD0001G_01_s_2012_23				
Comment Code					
EQ : Equipment					
Inspector Comment					
Remove equipment from the LS toe.					

Photo 1 of 1 : SP_2017_LD0001G_432_23_20170315_00009.jpg



View of the equipment along the landside toe.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	3.88	Rating **	A/W	Issue No.	395
LM End	3.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.523845 °	39.523845 °
				-122.010745 °	-122.010745 °
DWR ID	DWR_LD0001G_01_s_2012_395				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Unable to see the rodent holes because of the prunings pile. Backfill and compact the rodent holes on the landside slope.					

Photo 1 of 1 : SP_2017_LD0001G_432_395_20170315_00044.jpg



View of the rodent holes along the L/S toe.

LM Start	3.88	Rating **	M	Issue No.	52
LM End	3.88	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.523855 °	39.523855 °
				-122.010762 °	-122.010762 °
DWR ID	DWR_LD0001G_01_f_2014_52				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_52_20170315_00020.jpg



View of the prunings along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	3.98	Rating **	U	Issue No.	404
LM End	3.98	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.524990 °	39.524990 °
				-122.009575 °	-122.009575 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:51463 DS_ID:22904 EP_NO: 9572 Repair Type: Urgent Crossing Status: Found UCIP Comments: 12/21/2016 Flap gate on WS does not appear to be broken however, flap gate does not fully close due to a 3-inch aluminum pipe sleeve through larger pipe. Need to remove 3-inch pipe in order to have WS flap gate close and to be compliant with Title 23. (O. Magana - DWR UCIP)05/29/2013 Broken flap gate and Concrete headwall on LS toe possibly tilting. Also a 3-inch alluminum irrigation line through the pipe. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 18-inch steel drainage pipe through levee, 7.3 feet below crown. Flap gate in 6-inch by 6-inch concrete box located on the waterside (WS) end. Concrete headwall located on the landside (LS) toe. (18-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9572, 1974 - H. & A. Smith). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 4.05)]. FS Date: 12/21/2016					

LM Start	3.98	Rating **	U	Issue No.	404 (cont)
LM End	3.98	Issue Type +	Ma	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_51463_27386.jpg



Distribution box on WS toe.

Photo 2 of 3 : UCIP_SP_2017_51463_27385.jpg



Headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	3.98	Rating **	U	Issue No.	404 (cont)	
LM End	3.98	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			39.524990 °		39.524990 °
				-122.009575 °		-122.009575 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:51463 DS_ID:22904 EP_NO: 9572 Repair Type: Urgent Crossing Status: Found UCIP Comments: 12/21/2016 Flap gate on WS does not appear to be broken however, flap gate does not fully close due to a 3-inch aluminum pipe sleeve through larger pipe. Need to remove 3-inch pipe in order to have WS flap gate close and to be compliant with Title 23. (O. Magana - DWR UCIP)05/29/2013 Broken flap gate and Concrete headwall on LS toe possibly tilting. Also a 3-inch alluminum irrigation line through the pipe. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 18-inch steel drainage pipe through levee, 7.3 feet below crown. Flap gate in 6-inch by 6-inch concrete box located on the waterside (WS) end. Concrete headwall located on the landside (LS) toe. (18-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9572, 1974 - H. & A. Smith). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 4.05)]. FS Date: 12/21/2016						

Photo 3 of 3 : UCIP_SP_2017_51463_27384.jpg



Distribution box on WS toe with broken flap gate and 3-inch aluminum irrigation pipe.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	4.25	Rating **	M	Issue No.	405
LM End	4.25	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.527050 °	39.527050 °
				-122.005247 °	-122.005247 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:51284 DS_ID:22906 EP_NO: 1229 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 12/21/2016 same as last inspection. Crossing has been modified from original permit. Need to contact owner to determine permit number issued for modification and to determine current status of crossing. Crossing has been downgraded from Urgent to Non-Urgent due to no damage observed on levee slopes or crown. (O. Magana - DWR UCIP)05/30/2013 Gate valve broken off in concrete standpipe on WS shoulder. 8-inch aluminum pipe sleeved through pipe prevents closure of 18-inch pipe. All concrete standpipes have been modified or broken. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 16-inch concrete (not 18-inch asphalt dipped steel as referenced in permit or USACE O&M manual) irrigation pipe through the levee, 8.6 feet below the crown. Gate valve in concrete well located on the waterside (WS) slope. Pump, service pole, engine, and fuel tank 48-inch, and standpipe are located on the toe of the landside (LS) slope (Permit No. 1229, 1947 - R. T. Miller). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 4.33)]. FS Date: 12/21/2016					

Photo 1 of 3 : UCIP_SP_2017_51284_23594.jpg



Pump, standpipe, and gate valve on LS toe.

LM Start	4.25	Rating **	M	Issue No.	405 (cont)
LM End	4.25	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_51284_23593.jpg



Gate valve in Concrete riser on WSs houlder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	4.25	Rating **	M	Issue No.	405 (cont)	
LM End	4.25	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.527050 °		39.527050 °
				-122.005247 °		-122.005247 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:51284 DS_ID:22906 EP_NO: 1229 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 12/21/2016 same as last inspection. Crossing has been modified from original permit. Need to contact owner to determine permit number issued for modification and to determine current status of crossing. Crossing has been downgraded from Urgent to Non-Urgent due to no damage observed on levee slopes or crown. (O. Magana - DWR UCIP)05/30/2013 Gate valve broken off in concrete standpipe on WS shoulder. 8-inch aluminum pipe sleeved through pipe prevents closure of 18-inch pipe. All concrete standpipes have been modified or broken. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 16-inch concrete (not 18-inch asphalt dipped steel as referenced in permit or USACE O&M manual) irrigation pipe through the levee, 8.6 feet below the crown. Gate valve in concrete well located on the waterside (WS) slope. Pump, service pole, engine, and fuel tank 48-inch, and standpipe are located on the toe of the landside (LS) slope (Permit No. 1229, 1947 - R. T. Miller). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 4.33)]. FS Date: 12/21/2016						

Photo 3 of 3 : UCIP_SP_2017_51284_23592.jpg



8-inch pipe sleeved through 16-inch pipe at LS toe.

LM Start	4.93	Rating **	M	Issue No.	63
LM End	4.93	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.532719 °	39.532719 °
				-121.995849 °	-121.995849 °
DWR ID	DWR_LD0001G_01_f_2015_63				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Repair the erosion along the WS slope.					

Photo 1 of 1 : SP_2017_LD0001G_432_63_20170315_00030.jpg



View of the vehicle erosion along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	5.06	Rating **	M	Issue No.	57
LM End	5.06	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.534593 °	39.534593 °
				-121.995950 °	-121.995950 °
DWR ID	DWR_LD0001G_01_f_2013_57				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_57_20170315_00023.jpg



View of the vehicle erosion along the slope of the levee.

LM Start	5.08	Rating **	U	Issue No.	7
LM End	5.17	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.534741 °	39.536013 °
				-121.996024 °	-121.996702 °
DWR ID	DWR_LD0001G_01_f_2012_7				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_7_20170315_00003.jpg



View of the rodent hole along the levee slope.

LM Start	5.22	Rating **	U	Issue No.	67
LM End	5.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.536750 °	39.536750 °
				-121.997090 °	-121.997090 °
DWR ID	DWR_LD0001G_01_s_2016_67				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes on the LS slope need to be backfilled.					

Photo 1 of 1 : SP_2017_LD0001G_432_67_20170315_00034.jpg



View of the rodent holes along the landside slope.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	5.51	Rating **	A/W	Issue No.	406
LM End	5.51	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.540546 °	39.540546 °
				-121.998981 °	-121.998981 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14346 DS_ID:22907 EP_NO: 344 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 12-inch pipe through levee 6.5 feet below crown. Gate valve at toe of waterward slope. Air vent and pump at LS toe. (ABO No. 9566, 1974) (App. No. 344-Giesbrecht) Originally included in the 1960 O&M manual. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 5.61)]. FS Date: 5/30/2013					

Photo 1 of 3 : UCIP_SP_2017_14346_23601.jpg



Pump, vent, and pipe on LS toe.

LM Start	5.51	Rating **	A/W	Issue No.	406 (cont)
LM End	5.51	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_14346_23600.jpg



Gate valve on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	5.51	Rating **	A/W	Issue No.	406 (cont)	
LM End	5.51	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.540546 °	39.540546 °	
				-121.998981 °	-121.998981 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14346 DS_ID:22907 EP_NO: 344 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 12-inch pipe through levee 6.5 feet below crown. Gate valve at toe of waterward slope. Air vent and pump at LS toe. (ABO No. 9566, 1974) (App. No. 344-Giesbrecht) Originally included in the 1960 O&M manual. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 5.61)]. FS Date: 5/30/2013						

Photo 3 of 3 : UCIP_SP_2017_14346_23599.jpg



Gate valve on WS toe.

LM Start	5.55	Rating **	U	Issue No.	75
LM End	5.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.541110 °	39.541110 °
				-121.999348 °	-121.999348 °
DWR ID	DWR_LD0001G_01_f_2016_75				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Large rodent hole on the landside toe.					

Photo 1 of 1 : SP_2017_LD0001G_432_75_20170315_00039.jpg



View of the rodent holes along the landside slope.

* Location
 LS : Land Side N/A : Not Applicable
 WS : Water Side
 CR : Crown

** Rating
 A : Acceptable N : Not Inspected/Rated
 M : Minimally Acceptable C : Corrected
 U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
 Ma : Maintenance Deficiency
 Ob : Design & System Obsolescence
 En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	5.90	Rating **	M	Issue No.	54
LM End	5.90	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.545992 °	39.545992 °
				-122.001180 °	-122.001180 °
DWR ID	DWR_LD0001G_01_f_2014_54				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_54_20170315_00021.jpg



View of the prunings along the landside toe.

LM Start	6.18	Rating **	M	Issue No.	407
LM End	6.18	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.549911 °	39.549911 °
				-122.002102 °	-122.002102 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14352 DS_ID:22911 EP_NO: 5118 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: New gasline markers should be installed as existing signage has been sun faded FIELD_STRUCT_DESC: 1 of 2: 12.75-inch high pressure gas line through levee 3.0 feet below crown (Permit No. 5118, 1965). [Additional Reference(s): DWR Levee Log, 1992]. FS Date: 5/30/2013					

Photo 1 of 2 : UCIP_SP_2017_14352_23609.jpg



Gasline flags on LS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	6.18	Rating **	M	Issue No.	407 (cont)	
LM End	6.18	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.549911 °	39.549911 °	
				-122.002102 °	-122.002102 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14352						
DS_ID:22911						
EP_NO: 5118						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: New gasline markers should be installed as existing signage has been sun faded						
FIELD_STRUCT_DESC: 1 of 2: 12.75-inch high pressure gas line through levee 3.0 feet below crown (Permit No. 5118, 1965). [Additional Reference(s): DWR Levee Log, 1992].						
FS Date: 5/30/2013						

Photo 2 of 2 : UCIP_SP_2017_14352_23608.jpg



Gasline sign on WS shoulder.

LM Start	6.18	Rating **	M	Issue No.	408
LM End	6.18	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.549938 °	39.549938 °
				-122.002110 °	-122.002110 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:16224					
DS_ID:22937					
EP_NO: 5118					
Repair Type: Non-Urgent					
Crossing Status: Indicator Found					
UCIP Comments: Pipe needs new gasline markers as sign on WS shoulder is sunbleached and cannot be read.					
FIELD_STRUCT_DESC: 2 of 2: 12.75-inch high pressure gas line through levee 3.0 feet below crown (Permit No. 5118, 1965). Gasline sign on WS shoulder. [Additional Reference(s): DWR Levee Log, 1992].					
FS Date: 5/30/2013					

Photo 1 of 1 : UCIP_SP_2017_16224_27345.jpg



Gasline sign on WS shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	6.22	Rating **	M	Issue No.	47
LM End	6.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.550533 °	39.550533 °
				-122.002319 °	-122.002319 °
DWR ID	DWR_LD0001G_01_s_2014_47				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_47_20170315_00014.jpg



View of the rodent activity along the l/s slope.

LM Start	6.24	Rating **	M	Issue No.	76
LM End	6.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.550725 °	39.550725 °
				-122.002370 °	-122.002370 °
DWR ID	DWR_LD0001G_01_f_2016_76				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_76_20170315_00040.jpg



View of the rodent holes along the landside slope.

LM Start	6.30	Rating **	M	Issue No.	65
LM End	6.30	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.551665 °	39.551665 °
				-122.002639 °	-122.002639 °
DWR ID	DWR_LD0001G_01_f_2015_65				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the vegetation from the waterside slope and toe.					

Photo 1 of 1 : SP_2017_LD0001G_432_65_20170315_00032.jpg



View of the vegetation along the waterside slope and toe.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	6.30	Rating **	M	Issue No.	64
LM End	6.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.551666 °	39.551666 °
				-122.002639 °	-122.002639 °
DWR ID	DWR_LD0001G_01_f_2015_64				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Trim trees along the landside slope.					

Photo 1 of 1 : SP_2017_LD0001G_432_64_20170315_00031.jpg



View of the trees along the landside toe.

LM Start	6.38	Rating **	A/W	Issue No.	10
LM End	6.64	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.552691 °	39.556459 °
				-122.003063 °	-122.003831 °
DWR ID	DWR_LD0001G_01_s_2012_10				
Comment Code					
V8 : Environmental Requirements.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_10_20170315_00005.jpg



View of the Army Corps of Engineers mitigation site.

LM Start	6.38	Rating **	M	Issue No.	77
LM End	6.87	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.552745 °	39.559637 °
				-122.003003 °	-122.004800 °
DWR ID	DWR_LD0001G_01_f_2016_77				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Remove the vegetation from the waterside slope.					

Photo 1 of 1 : SP_2017_LD0001G_432_77_20170418_00122.jpg



View of the vegetation along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	6.49	Rating **	M	Issue No.	68
LM End	6.61	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.554356 °	39.556071 °
				-122.003150 °	-122.003760 °
DWR ID	DWR_LD0001G_01_s_2016_68				
Comment Code					
PR : Prunings					
Inspector Comment					

No Photos

LM Start	6.65	Rating **	U	Issue No.	69
LM End	7.75	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.556556 °	39.572335 °
				-122.003868 °	-122.004690 °
DWR ID	DWR_LD0001G_01_s_2016_69				
Comment Code					
DT : Ditch					
Inspector Comment					
Concrete lined and earthen ditch/canal at LS toe.					

Photo 1 of 2 : SP_2017_LD0001G_432_69_20170315_00035.jpg



Another view of the ag ditch looking upstream.

LM Start	6.65	Rating **	U	Issue No.	69 (cont)
LM End	7.75	Issue Type +	En	Location *	LS

Photo 2 of 2 : SP_2017_LD0001G_432_69_20170315_00036.jpg



View of the ag ditch looking downstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	6.73	Rating **	M	Issue No.	409
LM End	6.73	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.557721 °	39.557721 °
				-122.004267 °	-122.004267 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14373 DS_ID:22915 EP_NO: 1443A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe abandoned, but need to verify if it was abandoned properly. FIELD_STRUCT_DESC: 36-inch concrete encased pipe through levee, 9 feet below crown. Steel plate welded over pipe at landside (LS) toe. 3-inch steel vent pipe on LS toe. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 6.83)]. FS Date: 5/30/2013					

Photo 1 of 2 : UCIP_SP_2017_14373_23655.jpg



Pipe with steel plate welded over end on LS of levee crown.

LM Start	6.73	Rating **	M	Issue No.	409 (cont)
LM End	6.73	Issue Type +	En	Location *	LS

Photo 2 of 2 : UCIP_SP_2017_14373_23654.jpg



Pipe with steel plate welded over end on LS of levee crown.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

Levee District No. 0001 (Glenn County)

Slide gate in 36-inch CMP standpipe on WS slope

Page 33 of 62

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	6.90	Rating **	M	Issue No.	410 (cont)	
LM End	6.90	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.560072 °		39.560072 °
				-122.005039 °		-122.005039 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14384 DS_ID:22917 EP_NO: 9702 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Abandoned and should be done so properly. FIELD_STRUCT_DESC: 20-inch concrete encased steel irrigation pipe (not 24-inch pipe referenced in USACE manual) through levee, 7.2 feet below crown. Slant pump located on the waterside (WS) bank. Slide gate in 36-inch concrete standpipe on WS berm. (24-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9702, 1974 - J. & M. Bertapelle). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 7.01)]. FS Date: 5/30/2013						

Photo 3 of 3 : UCIP_SP_2017_14384_23662.jpg



Concrete standpipe off WS toe.

LM Start	8.05	Rating **	M	Issue No.	20
LM End	8.16	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.576580 °	39.578187 °
				-122.004962 °	-122.005218 °
DWR ID	DWR_LD0001G_01_s_2012_20				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_20_20170315_00008.jpg



View of the trees and vegetation along the waterside slope of the levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	8.47	Rating **	U	Issue No.	411
LM End	8.47	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.582275 °	39.582275 °
				-122.007449 °	-122.007449 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:51285
DS_ID:22918
EP_NO: 9563
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 12/21/2016 same as last inspection crossing is opened on both ends and damaged on WS slope is visible. According to LMA representative, Nick Henning, pipe appears to be abandoned. (O. Magana - DWR UCIP)05/31/2013 Pipe open on both ends and damaged on WS slope. Pipe should be abandoned properly if appropriate. (W. Wylie - DWR UCIP)
FIELD_STRUCT_DESC: *ABANDONED* 12-inch steel drainage pipe through levee, 5 feet below crown. Pipe open on both waterside (WS) and landside (LS) ends. One corrugated metal cutoff wall. (12-inch pipe authorized under Automatic Board Order (ABO) No. 9563, 1974 - County of Glenn). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 8.60)].
FS Date: 12/21/2016

LM Start	8.47	Rating **	U	Issue No.	411 (cont)
LM End	8.47	Issue Type +	Ma	Location *	WS

Photo 1 of 3 : UCIP_SP_2017_51285_23668.jpg



Pipe on LS slope.

Photo 2 of 3 : UCIP_SP_2017_51285_23667.jpg



Pipe on LS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	8.47	Rating **	U	Issue No.	411 (cont)	
LM End	8.47	Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.582275 °	39.582275 °	
				-122.007449 °	-122.007449 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:51285 DS_ID:22918 EP_NO: 9563 Repair Type: Urgent Crossing Status: Found UCIP Comments: 12/21/2016 same as last inspection crossing is opened on both ends and damaged on WS slope is visible. According to LMA representative, Nick Henning, pipe appears to be abandoned. (O. Magana - DWR UCIP)05/31/2013 Pipe open on both ends and damaged on WS slope. Pipe should be abandoned properly if appropriate. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: *ABANDONED* 12-inch steel drainage pipe through levee, 5 feet below crown. Pipe open on both waterside (WS) and landside (LS) ends. One corrugated metal cutoff wall. (12-inch pipe authorized under Automatic Board Order (ABO) No. 9563, 1974 - County of Glenn). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 8.60)]. FS Date: 12/21/2016						

Photo 3 of 3 : UCIP_SP_2017_51285_23666.jpg



Pipe on WS slope.

LM Start	8.83	Rating **	M	Issue No.	412
LM End	8.83	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.587028 °	39.587028 °
				-122.005609 °	-122.005609 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:16204					
DS_ID:23147					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Need to determine if this passes completely through levee and what Permit No. was issued for it.					
FIELD_STRUCT_DESC: 1.5-inch galvanized iron pipe through the levee 6-feet below the crown. 1-inch PVC irrigation line sleeved through this conduit.					
FS Date: 5/31/2013					

Photo 1 of 3 : UCIP_SP_2017_16204_27330.jpg



Pipe visible next to well with bucket over standpipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	8.83	Rating **	M	Issue No.	412 (cont)	
LM End	8.83	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.587028 °	39.587028 °	
				-122.005609 °	-122.005609 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:16204						
DS_ID:23147						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Need to determine if this passes completely through						
levee and what Permit No. was issued for it.						
FIELD_STRUCT_DESC: 1.5-inch galvanized iron pipe through the						
levee 6-feet below the crown. 1-inch PVC irrigation line sleeved						
through this conduit.						
FS Date: 5/31/2013						

LM Start	8.83	Rating **	M	Issue No.	412 (cont)
LM End	8.83	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_16204_27329.jpg



Pipe visible next to well with bucket over standpipe.

Photo 3 of 3 : UCIP_SP_2017_16204_27328.jpg



Pipe debris on WS slope may be indicator of pipe location on WS.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	8.84	Rating **	A/W	Issue No.	413 (cont)
LM End	8.84	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.587097 °	39.587097 °
				-122.005598 °	-122.005598 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:16226 DS_ID:22919 EP_NO: 9562 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch drainage pipe with 3/8-inch wall epoxy coated steel sleeved through existing 30-inch corrugated metal pipe through the levee, 15 feet below the crown. Flap gate located on the waterside (WS) end. Slide gate in 44-inch corrugated metal pipe (CMP) riser on WS slope. Concrete headwalls on both ends. Two corrugated metal cutoff walls. (24-inch pipe was authorized under Permit No. 9562-1, 2011 - Levee District No. 1 - Glenn County; original 30-inch pipe was authorized under Automatic Board Order (ABO) issued as Permit No. 9562, 1974 - L. R. Henrich). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 8.98)]. FS Date: 5/31/2013					

Photo 3 of 3 : UCIP_SP_2017_16226_27354.jpg



Slide gate in 44-inch CMP riser on WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Levee District No. 0001 (Glenn County)

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	9.49	Rating **	M	Issue No.	414 (cont)
LM End	9.49	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.596012 °	39.596012 °
				-122.002638 °	-122.002638 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14389 DS_ID:22920 EP_NO: 9560 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Heavy rust along springline of pipe. Pipe has slight deformation at centerline of levee, not noticable on crown. FIELD_STRUCT_DESC: 72-inch corrugated metal drainage pipe through levee, 15 feet below crown. Flap gate located on the waterside (WS) end. Slide gate in 8-inch corrugated metal pipe (CMP) riser on WS slope. Concrete headwalls on both ends. Two corrugated metal cutoff walls. (72-inch pipe authorized under Automatic Board Order (ABO) issued under Permit No. 9560, 1974 - J. & L. Friesen). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 9.64)]. FS Date: 5/31/2013					

Photo 3 of 3 : UCIP_SP_2017_14389_23684.jpg



Flap gate and headwall on WS toe.

LM Start	9.50	Rating **	A/W	Issue No.	8
LM End	10.40	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.596192 °	39.607288 °
				-122.002573 °	-121.994565 °
DWR ID	DWR_LD0001G_01_s_2012_8				
Comment Code					
V8 : Environmental Requirements.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_8_20170315_00004.jpg



View of the Army Corps of Engineers mitigation site.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	9.51	Rating **	M	Issue No.	78
LM End	9.91	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.596270 °	39.601582 °
				-122.002523 °	-121.999487 °
DWR ID	DWR_LD0001G_01_f_2016_78				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_78_20170315_00041.jpg



View of the waterside vegetation looking upstream.

LM Start	9.54	Rating **	M	Issue No.	11
LM End	9.64	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.596705 °	39.598066 °
				-122.002247 °	-122.001704 °
DWR ID	DWR_LD0001G_01_s_2012_11				
Comment Code					
DE : Debris					
Inspector Comment					
Landscaping materials: mulch, wood chips, rock baskets, stacks of pavestones					

Photo 1 of 1 : SP_2017_LD0001G_432_11_20170315_00006.jpg



View of debris along the toe of the levee.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	9.91	Rating **	A/W	Issue No.	415
LM End	9.91	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.601470 °	39.601470 °
				-121.999501 °	-121.999501 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14390					
DS_ID:22921					
EP_NO: 9559					
Repair Type: No Action Needed					
Crossing Status: Found					
UCIP Comments:					
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 11 feet below crown. Flap gate is located on the waterside (WS) end. Slide gate in 36-inch corrugated metal pipe riser on WS slope. Concrete headwalls on both ends. Two corrugated metal cutoff walls. (24-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9559, 1974 - D. & M. Giesbrecht). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 10.05)].					
FS Date: 5/31/2013					

LM Start	9.91	Rating **	A/W	Issue No.	415 (cont)
LM End	9.91	Issue Type +	Ma	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_14390_23690.jpg



Slide gate in 36-inch CMP riser on WS slope.

Photo 2 of 3 : UCIP_SP_2017_14390_23689.jpg



Concrete headwall and pipe at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Levee District No. 0001 (Glenn County)

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	9.93	Rating **	A/W	Issue No.	416 (cont)	
LM End	9.93	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			39.601659 °		39.601659 °
				-121.999209 °		-121.999209 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14559 DS_ID:22922 EP_NO: 9558 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 11 feet below crown. Flap gate is located on waterside (WS) end. Slide gate in 36-inch corrugated metal pipe riser on WS slope. Two corrugated metal cutoff walls. Concrete headwalls on both ends. (24-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9558, 1974 - D. Geis). Originally included in the 1960 O&M manual. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 10.08)]. FS Date: 5/31/2013 8:43:01 AM						

Photo 2 of 3 : UCIP_SP_2017_14559_23985.jpg



Slide gate in 36-inch CMP riser on WS slope.

LM Start	9.93	Rating **	A/W	Issue No.	416 (cont)
LM End	9.93	Issue Type +	Ma	Location *	LS

Photo 3 of 3 : UCIP_SP_2017_14559_23984.jpg



Pipe, flapgate, and headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	10.20	Rating **	M	Issue No.	417
LM End	10.20	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.604696 °	39.604696 °
				-121.996265 °	-121.996265 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:16205					
DS_ID:23148					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Need to determine Permit No. for crossing.					
FIELD_STRUCT_DESC: 6-inch steel conduit through the levee 8-inches below the crown. Pump, vent, filter, and siphon breaker on LS toe. 4-inch PVC irrigation line sleeved through conduit for vegetation rehabilitation on WS slope.					
FS Date: 5/31/2013					

Photo 1 of 3 : UCIP_SP_2017_16205_27333.jpg



Pump with siphon breaker, vent and filter on LS toe.

LM Start	10.20	Rating **	M	Issue No.	417 (cont)
LM End	10.20	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_16205_27332.jpg



Pipe on LS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	10.20	Rating **	M	Issue No.	417 (cont)	
LM End	10.20	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.604696 °	39.604696 °	
				-121.996265 °	-121.996265 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:16205						
DS_ID:23148						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Need to determine Permit No. for crossing.						
FIELD_STRUCT_DESC: 6-inch steel conduit through the levee 8-						
inches below the crown. Pump, vent, filter, and siphon breaker on LS						
toe. 4-inch PVC irrigation line sleeved through conduit for vegetation						
rehabilitation on WS slope.						
FS Date: 5/31/2013						

Photo 3 of 3 : UCIP_SP_2017_16205_27331.jpg



Cover over pipe on WS berm.

LM Start	10.41	Rating **	M	Issue No.	418
LM End	10.41	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.607474 °	39.607474 °
				-121.994410 °	-121.994410 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14561 DS_ID:22923 EP_NO: 9557 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: This pipe appears abandoned and should be done so properly. FIELD_STRUCT_DESC: 1 of 2: 10-inch irrigation pipe of unknown material through levee, 3.7 feet below crown. Pump on bank. Siphon breaker on waterside (WS) berm. One corrugated metal cutoff wall. Concrete distribution box at toe of landside (LS) slope (10-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9557, 1974 - R. & R. Weis). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 10.56)]. FS Date: 5/31/2013					

Photo 1 of 3 : UCIP_SP_2017_14561_23989.jpg



Concrete distribution box at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	10.41	Rating **	M	Issue No.	418 (cont)	
LM End	10.41	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.607474 °		39.607474 °
				-121.994410 °		-121.994410 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14561 DS_ID:22923 EP_NO: 9557 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: This pipe appears abandoned and should be done so properly. FIELD_STRUCT_DESC: 1 of 2: 10-inch irrigation pipe of unknown material through levee, 3.7 feet below crown. Pump on bank. Siphon breaker on waterside (WS) berm. One corrugated metal cutoff wall. Concrete distribution box at toe of landside (LS) slope (10-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9557, 1974 - R. & R. Weis). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 10.56)]. FS Date: 5/31/2013						


Photo 2 of 3 : UCIP_SP_2017_14561_23988.jpg



Concrete distribution box at LS toe with outlet from pipe through levee.

LM Start	10.41	Rating **	M	Issue No.	418 (cont)
LM End	10.41	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_SP_2017_14561_23987.jpg



10-inch steel pipe and 1.5-inch electrical conduit on WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	10.41	Rating **	M	Issue No.	419
LM End	10.41	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.607474 °	39.607474 °
				-121.994410 °	-121.994410 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14562					
DS_ID:22938					
EP_NO: 9557					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Abandoned and should be done so properly.					
FIELD_STRUCT_DESC: 2 of 2: 1.5 inch galvanized iron electrical					
conduit through the levee 3.0 feet below the crown (ABO No. 9557,					
1974). Originally included in the 1960 O&M manual. [Additional					
Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M					
Manual Unit 140, May 1960, (Station XX+XX)].					
FS Date: 5/31/2013					


Photo 1 of 2 : UCIP_SP_2017_14562_23991.jpg



Source at JP next to concrete distribution box at LS toe.

LM Start	10.41	Rating **	M	Issue No.	419 (cont)
LM End	10.41	Issue Type +	En	Location *	LS

Photo 2 of 2 : UCIP_SP_2017_14562_23990.jpg



Pipe visible off WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	10.43	Rating **	U	Issue No.	420
LM End	10.43	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.607688 °	39.607688 °
				-121.994278 °	-121.994278 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:51286

DS_ID:22924

EP_NO: 9556

Repair Type: Urgent

Crossing Status: Found

UCIP Comments: 12/21/2016 same as last inspection flap gate disabled in open position. Surface erosion observed on LS slope. Recommend repair on WS flap gate to be able to close flap gate. (O. Magana - DWR UCIP)05/31/2013 Flap gate dissabled in open position. Pipe rusted through at WS toe upstream of Flapgate. (W. Wylie - DWR UCIP)

FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 15 feet below crown. Flap gate is located on the waterside (WS) end. Slide gate is inside a corrugated metal pipe (CMP) riser located on the WS slope. Two CM cutoff walls. Concrete headwall is located on LS and under outlet at the WS toe. (24-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9556, 1974 - E. R & M. R. Cooper). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 10.59)].

FS Date: 12/21/2016

LM Start	10.43	Rating **	U	Issue No.	420 (cont)
LM End	10.43	Issue Type +	Ma	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_51286_24006.jpg



Drainage channel on LS toe.

Photo 2 of 3 : UCIP_SP_2017_51286_24005.jpg



Concrete headwall and pipe at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

Levee District No. 0001 (Glenn County)

Pipe and flapgate at WS toe.

No Photos

Page 51 of 62

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	11.02	Rating **	A/W	Issue No.	421
LM End	11.02	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.616041 °	39.616041 °
				-121.994450 °	-121.994450 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14565 DS_ID:22925 EP_NO: 9556 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 48-inch corrugated metal drainage pipe of unknown material through levee, 11 feet below crown. Flap gate on waterside (Ws) end. Concrete headwall on both ends. Slide gate in 60-inch diameter corrugated metal pipe (CMP) riser on WS slope (48-inch authorized under Automatic Board Order (ABO) issued under Permit No. 9556, 1974 - E. R. & M. R. Cooper). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 11.17)]. FS Date: 5/31/2013					

LM Start	11.02	Rating **	A/W	Issue No.	421 (cont)
LM End	11.02	Issue Type +	Ma	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_14565_24009.jpg



Drainage ditch on LS toe.

Photo 2 of 3 : UCIP_SP_2017_14565_24008.jpg



Slide gate in 60-inch CMP riser on WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	11.02	Rating **	A/W	Issue No.	421 (cont)	
LM End	11.02	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			39.616041 °	39.616041 °	
				-121.994450 °	-121.994450 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14565 DS_ID:22925 EP_NO: 9556 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 48-inch corrugated metal drainage pipe of unknown material through levee, 11 feet below crown. Flap gate on waterside (Ws) end. Concrete headwall on both ends. Slide gate in 60-inch diameter corrugated metal pipe (CMP) riser on WS slope (48-inch authorized under Automatic Board Order (ABO) issued under Permit No. 9556, 1974 - E. R. & M. R. Cooper). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 11.17)]. FS Date: 5/31/2013						

Photo 3 of 3 : UCIP_SP_2017_14565_24007.jpg



Flap gate and concrete headwall on WS toe.

LM Start	11.10	Rating **	U	Issue No.	66
LM End	11.18	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.617252 °	39.618192 °
				-121.994605 °	-121.995609 °
DWR ID	DWR_LD0001G_01_f_2015_66				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the waterside slope.					

Photo 1 of 1 : SP_2017_LD0001G_432_66_20170315_00033.jpg



View of the rodent holes along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	11.51	Rating **	M	Issue No.	48
LM End	11.57	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.622083 °	39.622821 °
				-121.998858 °	-121.999244 °
DWR ID	DWR_LD0001G_01_s_2014_48				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2017_LD0001G_432_48_20170315_00015.jpg



View of the rodent activity along the waterside slope.

LM Start	11.64	Rating **	A/W	Issue No.	422
LM End	11.64	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.623874 °	39.623874 °
				-121.999813 °	-121.999813 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14566 DS_ID:22926 EP_NO: 9555 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 8.5 feet below crown. Flap gate on waterside (WS) slope. U-shaped concrete headwalls on both ends. Two corrugated metal cutoff walls. (24-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9555, 1974 - F. S. Reager). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 11.81)]. FS Date: 5/31/2013					

Photo 1 of 3 : UCIP_SP_2017_14566_24013.jpg



Concrete headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	11.64	Rating **	A/W	Issue No.	422 (cont)	
LM End	11.64	Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			39.623874 °	39.623874 °	
				-121.999813 °	-121.999813 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14566 DS_ID:22926 EP_NO: 9555 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 8.5 feet below crown. Flap gate on waterside (WS) slope. U-shaped concrete headwalls on both ends. Two corrugated metal cutoff walls. (24-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9555, 1974 - F. S. Reager). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 11.81)]. FS Date: 5/31/2013						

Photo 2 of 3 : UCIP_SP_2017_14566_24012.jpg



Slide gate in 36-inch CMP riser on WS slope.

LM Start	11.64	Rating **	A/W	Issue No.	422 (cont)
LM End	11.64	Issue Type +	Ma	Location *	WS

Photo 3 of 3 : UCIP_SP_2017_14566_24011.jpg



Concrete headwall and flapgate on WS toe

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	11.66	Rating **	U	Issue No.	79
LM End	11.66	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.624112 °	39.624112 °
				-121.999933 °	-121.999933 °
DWR ID	DWR_LD0001G_01_f_2016_79				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes on the landside slope and crown.					

Photo 1 of 2 : SP_2017_LD0001G_432_79_20170315_00042.jpg



View of the rodent holes along the landside slope with large hammer sitting in the hole.

LM Start	11.66	Rating **	U	Issue No.	79 (cont)
LM End	11.66	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP_2017_LD0001G_432_79_20170315_00043.jpg



Another view of the rodent holes along the landside slope with a large hammer sitting next to the hole.

LM Start	11.67	Rating **	M	Issue No.	42
LM End	11.79	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.624171 °	39.625823 °
				-121.999967 °	-122.000834 °
DWR ID	DWR_LD0001G_01_s_2012_42				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	11.76	Rating **	M	Issue No.	423
LM End	11.76	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.625463 °	39.625463 °
				-122.000658 °	-122.000658 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14567 DS_ID:22927 EP_NO: 9554 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Erosion and sloughing on LS slope possibly due to rodent activity in area. FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 11 feet below crown. Slide gate in 36-inch corrugated metal pipe riser on waterside (WS) slope. 48-inch concrete standpipe on landside toe. Two corrugated metal cutoff walls. (24-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9554, 1974 - T. H. Reed). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 11.93)]. FS Date: 5/31/2013					

Photo 1 of 3 : UCIP_SP_2017_14567_24017.jpg



Concrete standpipe on LS toe.

LM Start	11.76	Rating **	M	Issue No.	423 (cont)
LM End	11.76	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_14567_24016.jpg



Slide gate in CMP riser on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	11.76	Rating **	M	Issue No.	423 (cont)	
LM End	11.76	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			39.625463 °	39.625463 °	
				-122.000658 °	-122.000658 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14567 DS_ID:22927 EP_NO: 9554 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Erosion and sloughing on LS slope possibly due to rodent activity in area. FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 11 feet below crown. Slide gate in 36-inch corrugated metal pipe riser on waterside (WS) slope. 48-inch concrete standpipe on landside toe. Two corrugated metal cutoff walls. (24-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9554, 1974 - T. H. Reed). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 11.93)]. FS Date: 5/31/2013						

Photo 3 of 3 : UCIP_SP_2017_14567_24015.jpg



Erosion and sloughing on LS slope possibly due to rodent activity.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	11.87	Rating **	M	Issue No.	424
LM End	11.87	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.626918 °	39.626918 °
				-122.001421 °	-122.001421 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14569 DS_ID:22928 EP_NO: 9554 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Flap gate heavily corroded. Good candidate for video inspection. Vegetation interfering with inlet. FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 7 feet below crown. Flap gate on waterside (WS) end. Slide gate in 36-inch corrugated metal pipe riser on WS slope. Concrete headwalls on both ends. Two corrugated metal cutoff walls. (24-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9554, 1974 - T. H. Reed). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 12.04)]. FS Date: 5/31/2013					

Photo 1 of 3 : UCIP_SP_2017_14569_24026.jpg



Slidegate in 36-inch CMP riser on WS slope.

LM Start	11.87	Rating **	M	Issue No.	424 (cont)
LM End	11.87	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_14569_24025.jpg



Drainage channel on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	11.87	Rating **	M	Issue No.	424 (cont)	
LM End	11.87	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			39.626918 °	39.626918 °	
				-122.001421 °	-122.001421 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:14569						
DS_ID:22928						
EP_NO: 9554						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Flap gate heavily corroded. Good candidate for video inspection. Vegetation interfering with inlet.						
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 7 feet below crown. Flap gate on waterside (WS) end. Slide gate in 36-inch corrugated metal pipe riser on WS slope. Concrete headwalls on both ends. Two corrugated metal cutoff walls. (24-inch pipe authorized under Automatic Board Order (ABO) issued as Permit No. 9554, 1974 - T. H. Reed). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 12.04)].						
FS Date: 5/31/2013						

Photo 3 of 3 : UCIP_SP_2017_14569_24024.jpg



Headwall and flapgate on WS toe.

LM Start	11.91	Rating **	M	Issue No.	44
LM End	11.97	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.627423 °	39.628278 °
				-122.001562 °	-122.001818 °
DWR ID	DWR_LD0001G_01_s_2012_44				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries partially block visibility.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	12.13	Rating **	A/W	Issue No.	425
LM End	12.13	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.630451 °	39.630451 °
				-122.002737 °	-122.002737 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14570 DS_ID:22929 EP_NO: 9554 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 7 feet below crown. Flap gate on waterside (WS) end. Slide gate in 36-inch corrugated metal pipe (CMP) riser on WS slope. U-shaped concrete headwalls on both ends. (24-inch pipe authorized under Automatic Board Order (ABO) issued under Permit No. 9554, 1974 - T. H. Reed). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 12.29)]. FS Date: 5/31/2013					

Photo 1 of 3 : UCIP_SP_2017_14570_24029.jpg



Flapgate and U-shaped concrete headwall on WS toe.

LM Start	12.13	Rating **	A/W	Issue No.	425 (cont)
LM End	12.13	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_14570_24028.jpg



Slidegate in 36-inch CMP riser on WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	03/28/2017 03/28/2017	Bob Duffey

LM Start	12.13	Rating **	A/W	Issue No.	425 (cont)
LM End	12.13	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.630451 °	39.630451 °
				-122.002737 °	-122.002737 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:14570 DS_ID:22929 EP_NO: 9554 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through levee, 7 feet below crown. Flap gate on waterside (WS) end. Slide gate in 36-inch corrugated metal pipe (CMP) riser on WS slope. U-shaped concrete headwalls on both ends. (24-inch pipe authorized under Automatic Board Order (ABO) issued under Permit No. 9554, 1974 - T. H. Reed). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 140, May 1960, (HLM 12.29)]. FS Date: 5/31/2013					

Photo 3 of 3 : UCIP_SP_2017_14570_24027.jpg



U-shaped concrete headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---